

TECH NOTE 021

ISSUE DATE: 10-Aug-06
EXEDY REF: 021
REVISED: 20-Jul-07

DAEWOO LANOS, LEGANZA, CIELO & ESPERO CLUTCH RELEASE SHAFT

WITH HYDRAULIC RELEASE MECHANISM

Please be advised that the Clutch Release Shaft and Lever assembly has a history of failure in that the weld securing the lever to the cross shaft is suspect.

It is recommended that the shaft be inspected and replaced if the lever is found to be in any position other than in line with the detent slot.

