

# TECH NOTE 031

ISSUE DATE: 21-November-08  
EXEDY REF: 031

## CSC2365 Installation Instruction Note

When replacing a concentric slave cylinder, please follow the instructions below to ensure correct operation-

- 1 All grease or dust contamination must be removed from inside the bell housing.
- 2 All retaining bolts must be located and torqued to the manufacturers specification.
- 3 An "O" ring is located between the CSC and transmission and it must be replaced to prevent fluid leak and hence clutch non release.
- 4 The cylinder should be installed without grease and do not clean the cylinder with solvent.
- 5 Use only virgin Dot 4 or the manufacturers recommended brake fluid.

