

TECH NOTE 041

ISSUE DATE : - 18/06/10

EXEDY REF : - 041

**Holden
Barina/Combo XC
GMK-7346**

GMK-7346

This kit may contain a cover assembly that has clips securing the pressure plate to the cover pressing during transport.

It is imperative that these clips (three of) be removed after the cover assembly is bolted to the flywheel.

Failure to remove the clips will result in major damage to the bell housing.

Should you have any queries regarding this technote, please contact your local Exedy distributor for further details.



EXEDY
No.1 for Clutch