

TECH NOTE L

ISSUE DATE: 13-Dec-04
EXEDY REF: L
REVISED: 15-Aug-05

NISSAN PATROL ERRATIC PEDAL FEEL (PEDAL GRAUNCH)

Nissan Patrol kit number involved NSK- 7130.

It has come to our attention that pedal graunch and an erratic pedal feel is apparent in these applications. To overcome and rectify this problem, we will now be supplying a self-aligning bearing which will eliminate the possibility of misalignment, which is the cause of the erratic pedal feel.

Misalignment is evident in some cases by red dust apparent on the diaphragm tip and bearing.

PLEASE ENSURE THE NEW BEARING IS PRESSED ON SQUARELY AND WITH GREAT CARE.

