



**Contact:**  
VIC: 03 9701 5556  
NSW: 02 9831 7771  
QLD: 07 3268 2640

www.exedy.com.au

## 2007 CATALOGUE

Please note the following amendments & tips applicable to our 2007 catalogue. We recommend that you update your catalogue to reflect these notes.

The amendment to page A45, **Ford Transit PETROL** is most important!

Page #	Comment
A15 / A16	Information on pages A15 and A16 is not aligned correctly. A bright yellow warning sticker supplied with your catalogue should be adhered to page A16.
A19	DAF F2300, 2305, DH825, DHU825, add "Lever Type Cover" to application detail against listing 380 x 1 3/4" x 10, cover assembly number 1882-328-031.
A19	DAF F2300, 2305, DH825, DHU825, add "Diaphragm Type Cover" to application detail against listing 380 x 1 3/4" x 10, cover assembly 3482-017-031.
A25 / A26	Daihatsu Terios J102, 1.3 Ltr. It has been identified that BRG2207 and reuse of the original clip can be used where occasionally BRG2344 as included in EAP kit DHK-7340, is not suited to the vehicle.
*A45*	Ford Transit, Petrol, 2.3 Ltr, 02-on. Line reading, Replacement kit to suit EAP rigid aftermarket flywheel reads use FMK-7502, it should read FMK-7503.
A49 / A50	Information on pages A49 and A50 is not aligned correctly. A bright yellow warning sticker supplied with your catalogue should be adhered to page A50.
A63	Barina XC, 1.6 Ltr, Z16SE with External slave cylinder, GMK-6527 should read GMK-6742.
A69	Near the top of page, add the vehicle details directly beneath the model heading Monaro CV8 which should read, "5.7 Ltr, LS1 Chev Engine, Gen 3, 6 speed".
A73	Near the top of page, the bold sub heading "6 CYLINDER MODELS" should read "8 CYLINDER MODELS"
A73 / A74	Holden Jackaroo & Monterey 4WD, 3.5 Ltr V6 6VE1, pull type (UBS26), 97-on GMK-7268. Add Spigot Bearing 6203DWAX.
A79	Honda Jazz, 1.3 Ltr, 16v, dimensional detail is, "190 x 22 x 20" please add.
A79	Honda Jazz, 1.5 Ltr, VTi, 16V, amend dimensional detail to read, "190 x 22 x 20".
A99 / A100	At line reading, "F1800, V8 Petrol with Lipe push type cover assembly 66-72" amend as follows: <ul style="list-style-type: none"> <li>Under column heading, Release Brg / CSC, replace 140-301-1527 with BRG2011.</li> <li>Under column heading, Spigot Bush / Brg, replace BRG2011 with 6205.</li> <li>Under column heading, Alignment Tool, replace 6205 with DCT-HT150.</li> <li>Under column heading, Flywheel Profile Dimension, replace DCT-HT150 with FLAT.</li> </ul>
A113	Last line on page reads FRR34 model, it should read FSS34.
A143	Mazda RX Series, directly above line reading, RX7, FD3S Twin Turbo, N3, pull type, 93-02, add bold sub heading, "Series 6, 7 & 8."

Page #	Comment
A153	Mercedes Benz. Addition of the following information in your catalogue may assist you identifying parts to suit these models. <ul style="list-style-type: none"> <li>▪ MB 100 2.3 Ltr Petrol (Solid Flywheel, Sprung Clutch Plate)</li> <li>▪ MB 100 2.3 Ltr Diesel (Solid Flywheel, Sprung Clutch Plate)</li> <li>▪ MB 100 2.9 Ltr Diesel (DMF, Rigid Centre Clutch Plate)</li> <li>▪ MB 140 2.3 Ltr Petrol (Solid Flywheel, Sprung Clutch Plate)</li> <li>▪ MB 140 2.9 Ltr Diesel (DMF, Rigid Centre Clutch Plate)</li> </ul>
A183	Mitsubishi FV Series, FV51J model, add to application information, "Air assisted hydraulic release mechanism"
A234	Add beneath the last information listed on page A234, * see page 241 – A242 for bearing sizes *. This note was inadvertently printed near the top of page A236.
A251	Hilux, 4 Runner, Surf, line reading GGN25R, 4.0 Ltr, V6, 1GRFE, 05 – on, add model GGN15R.
A253	Hilux, Diesel, two lines reading KUN16, and KUN26, 3.0 Ltr, 1KDFTV, Turbo, 05 – on, amend disc O.D. to read 260mm.
A259 / A260	Toyota Landcruiser HDJ100, 4.2 Ltr Turbo, 1HD-FTE, 3/98-on, add "Y" to column headed HD (Heavy Duty).
A267	VW Bora 2.3 Ltr V5cyl 110 Kw AGZ, DOHC, add O.E. is DMF.
A267	VW Golf 1.9 Ltr Turbo Diesel AGR, AHF, & ALH, 10/95 – 2/97, amend disc O.D. to read 228mm, and add kit number VWK-6513.
A275	Volvo F16, from chassis no. 382113, Kit # VLK-7170, add to the application details, "Spline saver type discs."
A275	Volvo FH12, Kit # VLK-7264, add to the application details, "Spline saver type discs." (In two places)
A277	Volvo FL12, Kit # VLK-7264, add to the application details, "Spline saver type discs."
A281	Volvo NL12, Kit # VLK-7264, add to the application details, "Spline saver type discs."
A277	Add sub heading FL60 SERIES above line reading, FL60, D6A225, Super Charged Turbo, 97-99.
A281	Volvo Commercial, relocate bold sub heading at top of page <b>N12 Series</b> directly above line reading N12, TD121F, R70, SR70 trans, (Volvo ref KF215D,G)
A281	Wolseley 24/80, MK1 & 11, 62-67, kit should read LYK-6397
D9	TYK-7678 size should read 260mm.
F11	Last line should read H19 in lieu of F36.
F20	The second last kit number listed reads GH01SD. It should read GT01SD, and the two discs assemblies listed should both read DT02D.
G57	Tech Note 022 can now be cancelled. EAP 2007 catalogue now lists MBK-7684 which includes the correct 230mm disc to suit this Magna application. (Page A169)



Contact:

VIC: 03 9701 5556

NSW: 02 9831 7771

QLD: 07 3268 2640

www.exedy.com.au