

TECH NOTE 032

ISSUE DATE: 27-January-09
EXEDY REF: 032

Thread Sealing Requirement

To prevent oil leaching from the crankcase which may contaminate the clutch, apply a suitable thread sealant to each bolt prior to installation.