

TECH NOTE 035

ISSUE DATE: 28-May-09
EXEDY REF:035

Holden Commodore VT-VE V8

Commodore VT-VE & Monaro CV8 Gen III (5.7Ltr) - Gen IV (6.0Ltr) Flywheel to crank bolts:

The bolts supplied in this kit should be tightened to 100Nm torque

To prevent oil leaching from the crankcase that may cause contamination of the clutch, apply suitable thread sealer to bolts before installation.