

TECH NOTE 039

ISSUE DATE : - 07/06/10

EXEDY REF : - 039

Holden Commodore V6 VS - VY

The flywheel included in this kit has a balance mass that compensates the internal "Out of Balance" moment within the Holden V6 engine.:-

Commodore VS II - VY V6 :-

The orientation of the flywheel to crankshaft is critical.

One (1) of the flywheel to crank holes is offset by a minor amount.

When installing the flywheel, introduce each bolt by hand. DO NOT USE AN IMPACT GUN, as it is possible to locate the flywheel 180 degrees out. Failure to position the flywheel correctly will result in chronic vibration.



EXEDY
No.1 for Clutch