

# TECH NOTE D

ISSUE DATE: 10-Dec-04  
EXEDY REF: D  
REVISED: 15-Aug-05

**NOT RECOMMENDED TO REPLACE TWIN  
CLUTCH SYSTEM**

Not recommended to replace  
twin clutch system.

No warranty if this clutch fitted  
where twin clutch system  
was used as original equipment.